



How to FIRE POCAHONTAS TYPE COALS

— CONICAL METHOD —

1. Heap fresh coal in the center in form of a CONE
2. Keep fire burning brightly around all sides of fire box.
3. Always control the heat by regulating all drafts and dampers.
4. Keep feed door and its slide closed.
5. Rock grates gently until first red sparks appear in ash pit
6. Leave some ashes on grates
7. Break down coked cone occasionally without stirring.
8. Don't burn garbage - this may cause clinkers.
9. Keep furnace and flues clean and in good répair.
10. Keep ash pit clean.
11. For rectangular fireboxes, the Coking Method should be used for Pocahontas Type Coals.

Issued by -
Chicago Smoke Abatement Fair Exhibit
Lock Box 1048
Chicago, Ill.

(All rights reserved)